

Your Ref :
Our Ref : PLS7/61/6/SC/iry/286
Date : 21 March 2014

YANGTZE THREE GORGES TECHNOLOGY & ECONOMY
DEVELOPMENT CO.LTD./THREE GORGES DEVELOPMENT
COMPANY (MALAYSIA) SDN.BHD.
Sublot 24, Lot 11442, Block 11,
Jalan Lorong Song 4, M.T.L.D.,
93350 Kuching, Sarawak.

Fax: 082-460959

Attn: Mr. Zhao Jianqiang

Dear Sir,

MURUM HYDROELCTRIC PROJECT
List of Action Points for Murum HEP Runner Inspection

Please find enclosed the List of Action Points for Managing Murum HEP Runner Inspection.

This document shall be the guideline in order for TGDCM to plan for runner inspections and repair work, and presents the minimum criteria that we require.

On top of that, we would also like TGDCM to consider these:

1. Organization plan, including management, foremen, quality control, welding technology, team of welders and grinders.
2. Plan of the power station showing where the runners, other equipment are placed and what civil building activities are planned during the inspection and rectification period.
3. Description of how ventilation of the work space will be solved and how the problem with gasses from the welding will be solved.
4. Drawings and templates defining the geometric shape of the welds and the blades near ring and crown.

Please be reminded that the criteria listed are not complete. TGDCM are obliged to consider these criteria and must supplement as needed to demonstrate that they will manage the works.

TGDCM are required to respond to this letter, supplemented with the required information and documentation by Wednesday, 26 March 2014.

Thank you.

Your Ref :
Our Ref : PLS7/61/6/SC/iry/286
Date : 21 March 2014
Page 2

Yours faithfully,

SARAWAK ENERGY BERHAD



Frankie Chin
Technical Manager
Murum Hydroelectric Project

Encl. 1. List of Action Points for Managing Murum HEP Runner
2. Presentation slides: Murum HEP - Turbine runners - Independent assessment